

Morley Memorial Primary School Proposed Redevelopment  
Feedback Forms Summary, November 2015

Topic	Comment	No. of Comments	Responses
Outdoor space	Restricting the outdoor space for pupils	23	The outside space over exceeds the minimum requirement on a confined site, even after the proposed development. The total amount of outside space will decrease however the amount of useable outside space will increase.
Environment	Flash Flood Prevention?	3	The 'flash flood' was the cause of hazardous weather conditions, however there will be no changes to the proposed plans to accommodate for extreme weather conditions as the likelihood of it happening again it extremely low.
	Lack off wildlife in the outdoor space		There are dedicated areas for wildlife in the proposed plans.
Transport	Dangerous / not safe when dropping off pupils	16	There is no proposal to change the current procedures. Any changes to the highway is outside the scope of the project.
	Limited parking for parents and staff		There is no increase in staff or pupil numbers, and the number of car parking facilities remain. On street parking is available in the surrounding streets which are currently not restrictive with residents parking. The School should continue to monitor staff parking and encourage wherever possible a public or other modes of transport including car sharing as part of their evolving travel plan. The new nursery will attract more staff, however the Traffic Impact Survey illustrates the impact of additional on street parking on the surrounding streets will be minimal.
Design	Insufficient toilets in proposed Building	16	School toilet provision complies with the new BB103 and Schools Premises Act. It should be noted that Accessible toilets can be used by staff, pupils and visitors and there are a greater number of these populated throughout the proposals for greater convenience.
	Too small to accommodate all the pupils		The school complies with school design guidance BB103.

	Rather poor, classrooms heat up and some of the windows need to be kept shut for extended time periods in order to prevent potential harm to students		School to explore ways to reduce temperature and increase ventilation where this is an issue
	No funding in sight to develop the coach house into the facilities necessary for pupils to be able to make good use of this area.		Correct, this was always on the School's wish list and is still something that they can develop in the future. The coach house is not required for the pupils to utilise the external space.
Construction	May cause major disruption to the main school building	1	Noted and it is the responsibility of the Contractor to ensure good communication with the School and neighbours to minimise disruption and cause the least inconvenience. The contractor has vast experience of working on live school sites.
Proposed Scheme	<p>Positive initiative &amp; resolves flaws at present</p> <p>Provides great new school space</p> <p>Best option and represents a great opportunity for the school</p> <p>A sensible solutions to the ongoing problems at the school</p> <p>The incorporation of the early years classes into the main site is a huge positive</p> <p>Resolves 'fear' of moving to a bigger school</p> <p>Good that the reception is having its own space within the main school</p> <p>Significantly enhance the educational provision of the school</p> <p>Good use of a 'folding wall' in the main hall to create more open space</p>	36	